HUGHES SERVICE INFORMATION LETTER

DATE June 8, 1966
PAGE 1 OF 1

TO-All owners and operators of Hughes Helicopters

SUBJECT:

INPUT SPLINE COUPLING P/N 5607 TIME INCREASE -

TAIL ROTOR TRANSMISSION

MODELS AFFECTED: All 269A, TH55A, 269A-1 and 269B Helicopters

Reference

Service Information Letter 2A-1058, 2A-1-1027, and 2B-1028 dated October 18, 1965

The Federal Aviation Agency has upped the life of the subject part from 970 to 1800 hours. As stated in the referenced service letter, the same increase was given to the transmission input shaft. The two parts noted are the items that limit the life of the transmission, therefore, the entire tail rotor transmission assembly has a FAA approved operating interval of 1800 hours.

HELICOPTER SUPPORT SERVICES . HUGHES TOOL COMPANY . AIRCRAFT DIVISION . CULVER CITY, CALIFORNIA